TABULATION OF BIDS			MATERIAL DESCRIPTION: Pump Repair Services						
RECOMMEND:	Shape Inc.		VENDOR:	Shape Inc.		Pump Repair Service, Co.		Koffler Electrical	
REASON:	Lowest responsible bid		ADDRESS:	119 Val Dervin Pkwy, Suite 2 Stockton, CA 95206		405 Allan Street Daly City, CA 94014		527 Whitney Street San Leandro, CA 94577	
			QUOTE DATE:	3/13/20)24				
				209-234-5909 Nich Chavez		415-467-2150 Wayne Archer		510-567-0690 Charlie Koffler	
				nchavez@shapecal.com		Jsedlack@pumprepairservice.com		NathanK@cokerpump.com	
ITEM#	QTY	DESCRIPTION		UNIT	TOTAL	UNIT	TOTAL	UNIT	TOTAL
1	1	Overhaul Flygt pump NP3300, 75 HP, incluimpeller with tungsten carbide coating, nevbearings, seals, o-ring kit, and labor. Impe All materials to be used will be OEM parts. fabrication or modification to pump is subjeapproval.	v insert ring, ller is hard iron. Any shop	Parts Lot: \$23,157 Labor Lot: \$2,500 Oil/Prep/Hazmat Fee: \$255	\$25,912.00				
2	1	Overhaul Flygt pump CP3201, 30 HP, incluimpeller, new wear ring, bearings, seals, of Impeller is cast iron. All materials to be usuparts. Any shop fabrication or modification to manufacturer approval.	ring kit, and labor. ed will be OEM	Parts Lot: \$17,618 Labor Lot: \$1,250	\$19,076.00				
3	1	Overhaul Flygt pump NP3152, 20 HP, incluimpeller, new wear ring, bearings, seals, of Impeller is hard iron. All materials to be us parts. Any shop fabrication or modification to manufacturer approval.	ring kit, and labor. ed will be OEM	Parts Lot: \$10,104 Labor Lot: \$1,000 Oil/Prep/Hazmat Fee: \$129	\$11,233.00				
4	1	Supply and replace the shaft sleeve and so Morse pump #8-C5425. Serial # of pump i materials to be used will be OEM parts. Ar or modification to pump is subject to manu	s: 234792-0. All ny shop fabrication	Shaft Sleeve: \$1,506 Mechanical Seal: \$4,951 Labor Lot: \$1,500	\$7,957.00				
5	1	Supply and replace the shaft sleeve and so Morse pump #8-5721. Serial # of pump is: materials to be used will be OEM parts. Ar or modification to pump is subject to manu	234953-0. All ny shop fabrication facturer approval.	Shaft Sleeve: \$1,506 Mechanical Seal: \$4,951 Labor Lot: \$1,500	\$7,957.00				
6	1	Resurface rotor, supply and replace stator #2E012Gl CDQ-X DAX. All materials to be parts. Any shop fabrication or modification to manufacturer approval.	used will be OEM	Rotor Resurface: \$980 Parts Lot: \$8,050 Labor Lot: \$1,500	\$10,530.00				
7	1	Supply rotary lobes and wear plates for NE Pump #T206/300 BD-E All materials to be parts. Any shop fabrication or modification to manufacturer approval	used will be OEM	Rotor: \$6,698 Elastomer Insert Cover: \$2,943 Elastomer Insert Housing: \$5,905	\$15,546.00				
			TOTAL:		\$98,211.00		No Bid		No Bid